

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	2107	(hing\$4 swing\$4 pivot\$4 rotat\$4) adj3 (printbar line pagewide pagewidth) with (print\$4 head)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:01			0
2	BRS	L2	6858	wip\$4 with cap\$4	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:01			0
3	BRS	L3	14	1 and 2	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:01			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	2107	(hing\$4 swing\$4 pivot\$4 rotat\$4) adj3 (printbar line pagewidth pagewidth) with (print\$4 head)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:01			0
2	BRS	L2	6858	wip\$4 with cap\$4	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:01			0
3	BRS	L3	14	1 and 2	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:01			0
4	BRS	L4	51239	(modul\$4 chip subhead subunit) near4 (printhead\$1 print\$4 head)	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:19			0
5	BRS	L5	434	2 and 4	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:19			0
6	BRS	L6	4	5 and 1	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/12/2 7 19:20			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
7	BRS	L7	92	1 and 4	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/27 19:22			0
8	BRS	L8	285	347/42.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/27 19:23			0
9	BRS	L9	2	7 and 8	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/27 19:23			0